HAZARDOUS MATERIALS CLASSIFICATION

HEALTH HAZARD

4-Deadly
3-Extreme danger
2-Hazardous
1-Slightly hazardous
0-Normal material

FIRE HAZARD
Flash Points

4-Below 73° F
3-Below 100° F
2-Below 200° F
1-Above 200° F
0-Will not burn

SPECIFIC HAZARD

Oxidizer	OX
Acid	ACID
Alkali	ALK
Corrosive	COR
Use NO WATER	W
Radiation Hazard	☢

INSTABILITY

4-May detonate
3-Shock and heat may detonate
2-Violent chemical change
1-Unstable if heated
0-Stable